SECTION 5: ANNOTATED LIST OF PROPERTIES

Photo	Location	Description
	Approx. 9650 - 9674 Main Street Date: c.1855 Use: Residential Condition: Alterations: Map – Grid 16	Running stone wall remains in segments.
	Approx. 9845 Main Street Date: c.1850 Use: Residential Condition: Alterations: Map – Grid 16	Stone wall running along the south side of Main between the Post Office and Kraus Road.
	Strickler / Mennonite Meeting House **10210 Main Street** Date: 1830 Use: Commercial Condition: Good Alterations: Historic adaptations and additions. Map – Grid 16	1½-story, side gabled, Colonial. Stone exterior with wood clapboard and vertical board. Old wood windowing. Front exterior stone chimney. Gabled dormers. Exterior copper lanterns and original water pump.

SECTION 5: ANNOTATED LIST OF PROPERTIES

	Approx. 10320-10330 Main Street Date: c.1870 Use: Residential Condition: Fair Alterations: Map –Grid 14:Clarence Hollow	Running stone wall remains.
 	10324 Main Street Date: c.1890 Use: Residential Condition: Good Alterations: Map –Grid 14:Clarence Hollow	2½-story, cross gabled, with mixed influence. Stucco exterior. Large porch. Nice detail, including: wrought iron work and molding. Roof dormers. Brick chimneys. Remaining outbuildings and entranceway. Running stone wall remains to the west possibly associated with.

SECTION 5: ANNOTATED LIST OF PROPERTIES

	10375 Main Street Date: 1890 Use: Residential Condition: Good Alterations: Small 1920s period. Map –Grid 14:Clarence Hollow	1½-story, side gabled, Colonial Revival Cape Cod. Wood clapboard exterior. Rough stone foundation and chimney. Front gabled dormer. Modest trim and detail. Running stone wall.
	Clarence Town Park **10405 Main Street** Date: 1900 Use: Municipal Condition: Good Alterations: Map –Grid 14:Clarence Hollow	Large open park. Running stone wall with entranceways.
	Clarence Town Park / former Automobile Club of Buffalo Clubhouse **10405 Main Street** Date: 1911 Use: Municipal Condition: Excellent Alterations: Map –Grid 14:Clarence Hollow	Set within park. Large, multiple hipped roof, Arts & Crafts style clubhouse. Stucco exterior. Original windowing and doors. Large intact porte cochiere with columns and rafter trails.

SECTION 5: ANNOTATED LIST OF PROPERTIES

 	Clarence Historical Museum **10465 Main Street** Date: 1844 Use: Municipal Condition: Excellent Alterations: Moved and added structures. Map –Grid 14:Clarence Hollow	**Local Historic Landmark Status** Authentically preserved, detailed, gabled Greek Revival of local Onandaga Limestone. Barns and outbuildings. On the museum grounds is the restored, best surviving pioneer Yankee log cabin in the county, the Goodrich – Landow Cabin, circa.1820. The cabin was moved here for educational purposes, its original location was on Goodrich Road near Lapp Road.
	10478 Main Street Date: 1808 Use: Residential Condition: Excellent Alterations: Modest historic changes and repairs. Map –Grid 14:Clarence Hollow	Fronts the side street. 2-story, cross gabled, Federal style. Lower stone exterior; wood shingle upper. Even fenestration; window shuttering. Simple trim and detail work. Private bricked courtyard. Large, cross gabled barn converted into garage.

SECTION 5: ANNOTATED LIST OF PROPERTIES

	**10522 Main Street** Date: c. 1910 Use: Residential Condition: Fair Alterations: Added carport. Some replaced windows. Map –Grid 14:Clarence Hollow	2-story, cross gabled, Queen Anne. Wood clapboard and decorative shingle exterior. Corner tower with copper roofing. Porch with ½-height columns on stone supports. Detail includes framing, end returns, and trim. 1½-story, front gabled, 2-car, early garage.
	Asa Ransom House **10529 Main Street** Date: 1853 Use: org. Residential now Commercial Condition: Excellent Alterations: Moved stone wall. Map –Grid 14:Clarence Hollow	**Clarence Historical Society Landmark** Large, 2½-story, cross gabled, Colonial. Several sections historically added. Exterior brick and wood clapboard. Good windowing; some arched. Shuttering. Moderate detail work.
	10536 Main Street Date: c.1890 Use: Residential Condition: Good Alterations: 1920s historic alterations, i.e. Porch. Map –Grid 14:Clarence Hollow	2½-story, front gabled, Victorian folk with period detailing and older Italianate influence. Wood clapboard and shingle exterior. Arched windowing with framing. Modest trim detail. Later enclosed porch. Carriage house / garage at rear.

SECTION 5: ANNOTATED LIST OF PROPERTIES

	10545 Main Street Date: 1821 Use: org. Residential now Commercial Condition: Fair Alterations: Vinyl siding. Historic rear additions; modern expanded and adapted to commercial use. Handicap access ramp. Map –Grid 14: Clarence Hollow	2-story, side gabled, frame Colonial structure. Intact, evolved character. Symmetric façade. Central entrance with elaborate enframement. Even, regular fenestration; matching façade bay windows. Large gable trim, moderate framing. Brick chimneys.
	**10548 Main Street** Date: c.1900 Use: Residential Condition: Good Alterations: Some replacement windows. Added shed dormer. Map –Grid 14: Clarence Hollow	2½-story, front gabled with extended sides, Single influenced. Wood shingle exterior. Even fenestration with framing and shuttering; some subtly arched. Entrance at east with large arched enframement, sidelights, and shutters. Large, front gambreled, wood shingled barn at rear.
	10553 Main Street Date: 1885 Use: Residential Condition: Good Alterations: Vinyl siding. Some replacement windows. Map –Grid 14:Clarence Hollow	2½-story, cross gabled, Queen Anne with mixed Stick influence. Excellent remaining character, styling, and detail.

SECTION 5: ANNOTATED LIST OF PROPERTIES

	10554 Main Street Date: 1915 Use: Residential Condition: Good Alterations: Map –Grid 14: Clarence Hollow	2½-story, cross gabled, Queen Anne. Wood clapboard and decorative shingle exterior. Hipped roof front porch with turned supports. Window enframements and modest additional detail. 1-story, flat roof with pent, garage and outbuilding.
	10560 Main Street Date: 1916 Use: org. Residential now Commercial Condition: Good Alterations: Map –Grid 14: Clarence Hollow	1½-story, complex hipped and cross gabled, Craftsman. Wood shingle exterior with stucco and half-timbering. Gabled entry porch. Character detailing. Newer outbuilding at rear.
	10575 Main Street Date: 1950 Use: Commercial Condition: Fair Alterations: Necessary tech. adaptations. Map –Grid 14: Clarence Hollow	1950s gas station. Concrete block and enamel exterior. Original garage doors.

SECTION 5: ANNOTATED LIST OF PROPERTIES

	10632 Main Street Date: 1900 Use: Commercial Condition: Good Alterations: Map – Grid14: Clarence Hollow	1-story, flat roofed with parapet, early 20th century commercial building. Concrete block and brick exterior. Symmetric storefront windows with recessed center entrance.
	10632 Main Street Date: 1900 Use: Residential/ Commercial Condition: Fair Alterations: Some replacement windows. Map – Grid14: Clarence Hollow	2½-story, cross gabled Queen Anne. Wood clapboard and shingle exterior. Old stone foundation. Modest detail.
	10654 Main Street Date: 1900 Use: Residential Condition: Fair Alterations: Vinyl siding. Map –Grid 14: Clarence Hollow	Unusual, 2-story, cross gambreled, mixed period style dwelling. Recently renovated with window replacement, chimney removed and vinyl sided